



SPECIAL FUNCTIONS

TO SWITCH OFF AFTER RECORDING WITHOUT SAVING THE FILES.



TO SWITCH ON AND SET PRESSURE ZERO.



PROBLEMS - Round and Square lamps flash together

○
□
Memory full

○ ○
□ □
Low battery

○ ○ ○
□ □ □
Probes missing

○ ○ ○ ○
□ □ □ □
Probes off scale
or faulty

○ ○ ○ ○ ○
□ □ □ □ □
Electronic fault